# **Administrative Requirements**

Public Entity	City of Morganton	Date	3/17/21		
_					(000)
Contact Person	Andy Smith	Email	asmith@morgantonnc.gov	Phone	(828) 438-5279

Title II requires that public entities undertake five administrative steps to promote implementation of the ADA.

Questions		Comments	Next Steps
Has a self-evaluation been conducted?  (Required no matter the number of employees.)	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
<ol> <li>Is public notice that the public entity does not discriminate on the basis of disability provided in print and audio formats?         (Required no matter the number of employees.)</li> <li>Methods may include the website, social media such as Twitter and Facebook, print notices at facilities and in local newspapers, program announcements, public service announcements on local radio and</li> </ol>	Yes No	Click here to enter text.	Click here to enter text.
<ul><li>television stations.</li><li>3. Has a grievance procedure been adopted to resolve disability-related complaints? (Required if 50 or more employees.)</li></ul>	Yes No 🗆	Click here to enter text.	Click here to enter text.
Has at least one employee been appointed to coordinate the public entity's ADA obligations - ADA Coordinator? (Required if 50 or more employees.)	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.

Appendix A

Questions		Comments	Next Steps
5. Has a transition plan been developed to address barriers in facilities that affect equal participation of people with disabilities in the public entity's programs, activities and services? (Required if 50 or more employees.)	Yes ∠ No ∟	Click here to enter text.	Click here to enter text.

# **Effective Communication**

Public Entity (	ublic Entity City of Morganton D				3/17/21
Contact Person	Andy Smith	Email	asmith@morgantonnc.gov	Phone	(828) 438-5279

Many people who are blind or have low vision, who are deaf or hard of hearing or who have other communication disabilities are prevented from participating fully in programs, activities and services because of communication issues. To address this Title II requires that communication with people with disabilities be "as effective" as communication with others. Often good communication practices will suffice, such as not turning away when speaking with a person who is hard of hearing or taking the time to listen to a person who has a speech impairment. Other times a public entity needs to provide "auxiliary aids and services" to ensure that communication is effective.

Questions		Comments	Next Steps
<ul> <li>Auxiliary Aids and Services</li> <li>Use the Comments column to indicate how aides and services are provided.</li> <li>For example: Arranged through State Commission for the Deaf, rented from XYZ Company, available from the County Disability Office.</li> <li>1. Does the public entity know how to provide the following for people who are deaf or hard of hearing:</li> </ul>			
a. Sign language, oral, and cued speech interpreters	Yes ⊠ No □	Click here to enter text.	Click here to enter text.
b. Video remote interpreting (VRI) services	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.

Qı	uestions		Comments	Next Steps
	c. Computer-assisted real-time transcription (CART) services	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
	d. Assistive listening devices	Yes 🗌 No 🗵	Due to lack of use and age they were surplused	We are currently running the meetings louder to help, but will look into purchasing more ALD's. Make and model of ALD's has been identified and could be ordered at a moment's notice if needed.
	e. Open and closed captioning of videos	Yes 🛛 No 🖾	We have closed captioning on all post production videos, but not live videos.	Click here to enter text.
	f. Real time captioning of television programs	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
	g. Other:	Yes 🗌 No 🗌	Click here to enter text.	Click here to enter text.
2.	Does the public entity know how to provide documents in the following formats for people who are blind or visually impaired and others with print disabilities:			
	a. Braille	Yes 🛛 No 🗌	Vendors have been identified to provide this service when needed.	Click here to enter text.

Questions		Comments	Next Steps
b. Large print	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
c. Audio recordings	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
d. Accessible electronic formats that that can be accessed by screen reading software, for example, documents in plain text or HTML	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
e. Screen reader software installed on a computer that is used by the public, for example in a library	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
f. Magnification software installed on a computer that is used by the public, for example in a computer lab	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
g. Optical readers	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
h. Other	Yes 🗌 No 🗍	Click here to enter text.	Click here to enter text.
Policies and Procedures			
3. Does the public entity have a policy or procedure to handle requests for auxiliary aids and services?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
4. Are employees and officials aware of the public entity's obligation to provide auxiliary aids and services?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.

Qı	uestions		Comments	Next Steps
5.	Do employees and officials know how to arrange for auxiliary aids and services?  Arrangements could be made directly or through the ADA coordinator or another staff person.	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
6.	Does the public entity give primary consideration to the person with a disability when determining what type of auxiliary aid or service to provide?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
7.	Are employees and officials aware that it is inappropriate to request that family members and friends of people who are deaf serve as sign language interpreters, except in emergencies or if the individual wants the family member or friend to interpret and it's appropriate to do so?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
8.	Are employees and officials aware that a companion of a program participant has a right to auxiliary aids and services if the companion has a communication disability and is an appropriate person with whom the public entity should or would communicate?  Example: A deaf family member of a hospital patient might need a sign language interpreter to communicate with the doctor.	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
9.	Are captions and audio description provided on videos and television programs the public entity produces and videos on its website?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.

Questions		Comments	Next Steps
<ul> <li>10. Does the public entity have a policy or procedure for determining if an auxiliary aid or service would be an undue financial and administrative burden?</li> <li>The decision of undue hardship must be made by the head of the public entity or his or her designee. There must be a written statement explaining the reasons for reaching that decision.</li> </ul>	Yes 🗌 No 🗵	Situations are reviewed on a case by case basis.	Click here to enter text.
Telecommunications			
11. Do employees and officials know how to respond to telephone calls made through Video Relay Services and Telecommunication Relay Services so that the calls are responded to in the same manner as other telephone calls?	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
12. Where telephones are available to the public for making outgoing calls, such as in hospital waiting rooms, are TTYs available for people with hearing and speech disabilities?  A TTY is an electronic device for text communication over a telephone line that is designed for use by people with hearing or speech disabilities.	Yes 🗌 No 🗵	TTY is not available on public phones.	Click here to enter text.
13. Do telephone emergency services, including 911, provide direct access to people who use TTYs and computer modems?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
Other Click here to enter text.			

# **General Nondiscrimination**

Public Entity	City of Morganton			Date	3/17/21	
_						
Contact Person	Andy Smith	Email	asmith@morgantonnc.gov	Phone	(828) 438-5279	

Title II of the ADA requires that people with disabilities are assured an equal opportunity to participate in the services, programs and activities offered by public entities. This part of the Title II regulations covers a wide range of issues as you will see from the questions below.

Questions		Comments	Next Steps
<ol> <li>Do policies, practices and procedures provide an equal opportunity for people with disabilities to participate in services, programs and activities; that is, do policies not discriminate against people on the basis of disability?</li> </ol>	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
Examples: A school district requires that students with autism have a parent accompany them on school trips. This is a discriminatory practice.			
A city has a policy that applicants for a hunting license have a valid, state-issued driver's license. This is a discriminatory policy.			
Are there circumstances in which the participation of a person with a disability would be excluded or restricted?	Yes 🛛 No 🗆	Click here to enter text.	Click here to enter text.
3. If yes, are the exclusions or restrictions necessary to the operation of the program or to the safety of other participants?	Yes 🛛 No 🗆	Restrictions are possible based on insuring safety for all	Click here to enter text.
Please explain:		participants. Each	

Q	uestions		Comments	Next Steps
			situation is evaluated individually with the intent to make reasonable accommodation for any disabilities while insuring a safe experience.	
4.	Are there separate services, programs or activities for people with disabilities or a class of people with disabilities?	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
	Examples: A municipal recreation department has a wheelchair basketball program. A county museum has a tour for people who are blind with an opportunity to touch sculptures. These are not discriminatory.			
	If yes, please describe:			
Co	ontracting with External Organizations			
5.	Do all employees who contract with outside agencies, organizations or businesses know that the public entity's ADA obligations apply whether the public entity provides the service, program or activity directly or contracts for it?	Yes 🗵 No 🗌	Click here to enter text.	Click here to enter text.
	Example: If a state department of emergency services funds a private organization to provide emergency shelters, the department maintains its ADA obligations to make sure people with disabilities receive the same services as people without disabilities.			
6.	Does the public entity notify each contractor of its responsibilities for	Yes 🛛 No 🗌	This is included in our contracts.	Click here to enter text.

Q	uestions		Comments	Next Steps
	providing contracted services in a nondiscriminatory manner?			
	If yes, please describe:			
7.	Does the public entity require assurances from contractors of their fulfillment of Title II requirements?	Yes 🛛 No 🗆	Contractors are bound by the terms of the contract which include nondiscrimination language.	Click here to enter text.
8.	Are there procedures to ensure that contractors provide the services, programs and activities in a nondiscriminatory manner consistent with the Title II requirements?	Yes 🗵 No 🗌	This is encompassed in Affidavit A – Listing of Good Faith Efforts in the contract.	Click here to enter text.
	If yes, please describe:			
Re	easonable Modifications			
9.	Are employees and officials aware that the public entity is obligated to make a reasonable modification in policies, practices, or procedures if the modification is necessary for a person with a disability to participate?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
	Example: No food or beverages are allowed to be consumed at a regional transit authority's subway stations or in subway cars. In order to control blood sugar levels, a person with diabetes might need to drink juice. This would probably be a reasonable modification of a policy.			
	ervice Animals (Under Titles II and III only dogs can be service animals. iniature horses can be service animals in some circumstances.)			
10	). Are employees and officials aware that:		Click here to enter text.	Click here to enter text.

Ques	tions		Comments	Next Steps
a.	The public entity must allow service animals to accompany people with disabilities in all areas where people without service animals are allowed to go?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
b.	Only two questions may be asked: (1) Is the dog a service animal required because of a disability? and (2) What work or task has the dog been trained to perform?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
C.	The public entity may not ask about a person's disability, require medical documentation, require a special identification card or training documentation for the dog, or ask that the dog demonstrate its ability to perform the work or task?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
d.	A person with a disability cannot be asked to remove his service animal from the premises unless: (1) the dog is out of control and the handler does not take effective action to control it or (2) the dog is not housebroken and, in these circumstances employees must offer the person with the disability the opportunity to obtain goods or services without the animal's presence?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
e.	The public entity must permit a miniature horse to accompany a person with a disability where reasonable?  Assessment factors include, the size and weight, whether the horse is housebroken, and whether its presence compromises safety requirements.	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
Whee	elchairs and Other Power-Driven Mobility Devices			
	re employees and officials aware that:  People with mobility disabilities may use wheelchairs, scooters and	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
a.	Topic with mobility disabilities may use wheelchairs, scooters and			

Ques	tions		Comments	Next Steps
	manually-powered mobility aids, such as walkers, crutches, canes, braces, or other similar devices designed for use by individuals with mobility disabilities in any areas open to pedestrian use?			
b.	People with mobility disabilities may use other power-driven mobility device in any areas open to pedestrian use unless the public entity can demonstrate that the class of other power-driven mobility devices cannot be operated in accordance with legitimate safety requirements?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
	Other power-driven mobility device means any mobility device powered by batteries, fuel, or other engines—whether or not designed primarily for use by individuals with mobility disabilities—that is used by individuals with mobility disabilities for the purpose of locomotion, including golf cars, electronic personal assistance mobility devices, such as the Segway® PT, or any mobility device designed to operate in areas without defined pedestrian routes, but that is not a wheelchair within the meaning of Title II.			
	Some of the factors that go into determining "legitimate safety requirements" include: size and speed of the device, the facility's design and characteristics (outdoor, indoor), and risk of harm to the immediate environment.			
C.	They may not ask about the nature and extent of the individual's disability, but may ask an individual to provide a credible assurance that the mobility device is required because of the person's disability?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
	Credible assurance includes a state-issued, disability parking placard or card, or other state-issued proof of disability or a verbal representation, not contradicted by observable fact, that the other			

Questions		Comments	Next Steps
power-driven mobility device is being used for a mobility disability.			
Surcharges and Costs			
12. Are employees and officials aware that the public entity may not place a surcharge on people with disabilities to cover the costs of measures, such as the provision of auxiliary aids or program accessibility, that are required to provide nondiscriminatory treatment?	Yes 🗵 No 🗖	Click here to enter text.	Click here to enter text.
Examples: Charging a person who is hard of hearing for the cost of providing an assistive listening system for a state hearing.  A housing authority requires an additional damage deposit if tenants have service animals. These are discriminatory policies.			
Ticketing (Not parking tickets, tickets for events that have seating.)			
13. Are tickets for accessible seats sold during the same hours; through the same methods of purchase (by telephone, on site, through a website, or through third-party vendors); and during the same stages of sales (presales, promotions, general sales, wait lists, or lotteries) as non-accessible seats?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
14. If accessible seating is not available in areas of the venue with lower prices, is lower priced accessible seating available in higher priced locations?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
15. Do venues and third-party sellers provide the same information about accessible seats as provided about non-accessible seats?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
Example: Maps or displays of seating configurations must include information on accessible seating.			

Questions		Comments	Next Steps
16. Can ticket sellers describe accessible seating in enough detail to permit the purchaser to determine if a seat meets his or her needs?	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
17. Do ticket sellers know that people purchasing a ticket for a wheelchair space may purchase up to three additional seats for their companions as close as possible to the wheelchair space and that these companion seats may include wheelchair spaces?	Yes 🗵 No 🗖	Click here to enter text.	Click here to enter text.
<ul> <li>18. Do ticket sellers know that unsold accessible seats may be released and sold to members of the general public in only one of three circumstances:</li> <li>when all non-accessible seats have been sold (excluding luxury boxes, club boxes, suites, and seats the venue holds back when declaring a sell-out); or</li> <li>when all non-accessible seats in a particular seating section have been sold; or</li> <li>when all non-accessible seats in a particular price category have been sold?</li> </ul>	Yes 🛛 No 🗖	Click here to enter text.	Click here to enter text.
19. If the venue permits patrons to give or sell their tickets to others, does the venue know that the same right must be extended to patrons with disabilities and that those tickets may be sold to someone who does not have a disability?  A venue may choose to move a patron to another seat in order to give that accessible seat to a patron with a disability who requires it, but is not obligated to do so.	Yes 🗵 No 🗆	Click here to enter text.	Click here to enter text.
20. Do ticket sellers know that for single event tickets, venues may ask purchasers to state that they require, or are purchasing tickets for someone who requires, the features of an accessible seat?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.

Questions		Comments	Next Steps
21. Do ticket sellers know that for series of events tickets, purchasers may be asked to attest in writing that they require, or are purchasing tickets for someone who requires, the features of an accessible seat?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
Other			
22. Is information about the public entity's accessible services, activities and facilities available to the public and to current and future program participants?	Yes 🛛 No 🗌	Click here to enter text.	Click here to enter text.
Example: A state department of recreation includes information about accessible swimming pools, fishing piers, boat launches, picnic and camping areas on its website and in a brochure.			

# **Website Accessibility**

Public Entity	City of Morganton			Date	3/17/21
				_	
Contact Person	Andy Smith	Email	asmith@morgantonnc.gov	Phone	(828) 438-5279

Many people with disabilities use assistive technology such as screen readers, text enlargement software, and programs that enable people to control the computer with their voice, eyes or nose. Access problems occur when website designers assume that everyone sees and accesses a webpage in the same way. Accessible website design recognizes these differences and does not require people to see, hear, or use a standard mouse in order to access the information and services provided.

Questions		Comments	Next Steps
<ol> <li>Is there a policy that the public entity's webpages will be accessible, that is, in compliance with the W3C Web Content Accessibility Guidelines (WCAG) 2.0 or Section 508 Standards?</li> </ol>	Yes No 🗵	Website is currently being updated to address content accessibility. Should be completed in August of 2021.	Click here to enter text.
2. Are the staff and contractors who are responsible for webpage and content development aware of the policy?	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
Are the staff and contractors who are responsible for webpage and content development knowledgeable about these standards?	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.
Has the website been tested for compliance with either of these standards?	Yes 🗌 No 🗵	Click here to enter text.	Click here to enter text.

Appendix D

Questions		Comments	Next Steps
5. If yes, have people with disabilities who use screen reading software and other assistive technology participated in the evaluation?	Yes 🗌 No 🗌	Click here to enter text.	Click here to enter text.
6. Is there a plan for making the existing web content accessible?	Yes 🖾 No 🗆	The City of Morganton is currently under contract with Municode to create new city pages. These pages will conform to all of the standards.	Updated webpage should be going live in August of 2021.
7. Is there a plan for making future web content accessible?	Yes ⊠ No □	Click here to enter text.	Click here to enter text.
Other: Click here to enter text.	Yes 🗌 No 🗌	Click here to enter text.	Click here to enter text.

Location		Deficiency		Correction	Criteri	ia - Low(	4+ yrs), I	Medium(1-3), Hig	gh(<1yr)	Finalized A	ctions	Additional Comments		
ADAAG Reference			Date Reviewed  Priority (Overall)  Public Access S  Public Access S  Approximate Cost to City											
ADAA	Facility Name	Area	Date	Description	Barrier	Recommended Correction	Priori	Public	Frequ	Appro		Finalized Correction	Date Corrected	Comments
3.19	Aquatic Center	Bathrooms	6/5/2020	All mirrors	Mirror currently at 43"	Lower mirror to 40"	M	M	M	Time				
3.20	Aquatic Center	Bathrooms	6/5/2020	Coat Hooks in bathroom stalls	Currently 60" high	Lower to a max of 48"	М	М	М	Time				
3.33	Aquatic Center	Bathrooms	6/5/2020	Side Grab Bars in bathroom stalls	Currently 53" from wall	Move down 1" to reach 54" from the wall	L	L	L	Time				
3.37	Aquatic Center	Bathrooms	6/5/2020	Flush control on the toilet	On the closed side	Move flush control to the open side of the stall	L	L	L	\$120-\$500 per toilet				
3.43	Aquatic Center	Bathrooms	6/5/2020	Door isn't self-closing	Door stays open	Change hinges to self closing			l ,	\$5-\$35 per stall				
P67	Aquatic Center	Pool	6/5/2020	Width between handrails entering pool	1 - 32"; 1 - 17"	Correct rails to be between 20" - 24" to enter pool	М	М	М					
P75	Aquatic Center	Pool	6/5/2020	Tread depth needs to be wider	Tread depth 10" on stairs	Alter treads to be wider	М	М	М	Approx. \$4,000				
P79	Aquatic Center	Pool	6/5/2020	Riser should be solid	Riser is currenlty open	Replace Risers	М	М	М	Ap \$4			<u> </u>	
1.11	Bethel Park	Parking Lot	6/23/2020	Van Accessible Signs	No current signs	Add Van Accessible signs to appropriate places	М	М	М	\$20 per space				Look to relocate bathroom to the bottom
3.3	Bethel Park	Bathrooms	10/27/2020	Handicap Accessible Signs	No current signs	Add Handicap Accessible signs	L	L	L	\$20 per bathroom				of the hill when remodeling the park
3.4	Bethel Park	Bathrooms		Difficult to enter	Hill, ramp, and a step	See Comments	M	M M	M M	Ti				
3.20 3.26	Bethel Park Bethel Park	Bathrooms Bathrooms	10/27/2020 10/27/2020	Coat Hooks in bathroom stalls  Pipes under the sink	Currently 66" high Unprotected pipes	Lower to a max of 48" Insulate/protect the pipes	M	M	M	Time \$20 - \$40				
3.28	Bethel Park		10/27/2020	Soap Dispenser	No soap dispenser	Install dispenser no higher than 48"	М	м	М	\$20				
3.30	Bethel Park	Bathrooms	10/27/2020	Location of toilet	Currently 24" from wall	Move to be between 16"-18" from the wall	М	М	М	\$2,500 - \$3,500 per toilet				
3.34	Bethel Park	Bathrooms	10/27/2020	Back Grab bar location	Currently centered on toilet	Move to have 12" past the center and 24" in the other direction	М	М	М	Time				
1.2	Carbon City Park	Parking Lot	7/23/2020	Handicap Parking	No handicap parking	Restripe the parking lot to allow for handicap parking and signs Add ADA bathrooms signs in	M	М	М	\$400 - \$500 \$20 per				Look to remodel the bathrooms when the park is updated per master plan
3.5	Carbon City Park	Bathrooms	1/4/2021	Bathroom Signs	Incorrect Signs	the proper position	М	М	М	bathroom				piaii
						Ramp the walkway to account				Approx. \$4,000 per				
3.8	Carbon City Park	Bathrooms	1/4/2021	Bathroom Entrance	High Threshold/Step	for the increase	М	М	М	door				
3.12	Carbon City Park Carbon City Park	Bathrooms Bathrooms		Bathroom Entrance Bathroom Sink	Door Closer Unprotected pipes	Extend the time of the door closing to at least 5 sec Insulate/protect the pipes	M M	M	M M	Time \$20 - \$40				
5.20	conson sity runk	500001113	5/2 1/2021	Such Sulf Silk	onprocessed pipes	Handles need to be able to be operated without tight			,	Ç20 Ç40				
3.27	Carbon City Park	Bathrooms		Bathroom Sink	Faucet	grasping	М	М	М	\$25 - \$50				
3.28	Carbon City Park	Bathrooms	5/24/2021	Bathroom Sink	Soap Dispenser	Add a soap dispenser	L	L	L	\$100 - \$200				
3.29	Carbon City Park	Bathrooms	5/24/2021	Bathroom Sink	Hand Dryer	Add a Hand Dryer/Paper Towels	L	L	L	\$50 - \$200				
3.30	Carbon City Park	Bathrooms	5/24/2021	Toilet	Toilet Location	Toilet is more than 16 - 18" from side wall	М	М	М	\$2,500 - \$3,500 per toilet				
3.32	Carbon City Park	Bathrooms	5/24/2021	Toilet	Toilet Height	Toilet should be 17" - 19" high Might reach height with a toilet seat added	М	М	м	\$20 - \$50				
3.33	Carbon City Park	Bathrooms	5/24/2021	Side Grab Bars in bathroom stalls	Missing Side Grab Bar	Add a Side Grab Bar	M	M	M	\$30 - \$50				
3.34	Carbon City Park	Bathrooms	5/24/2021	Rear Grab Bars in bathroom stalls	Missing Rear Grab Bar	Add a rear Brab Bar	М	М	М	\$30 - \$50			_	
3.19	Catawba Meadows Baseball Fields	Bathrooms	12/4/2020	All mirrors	Mirror currently at 50" high	Lower the mirror to 40" high or add another mirror	М	М	М	Time/\$30 - \$90				
3.23	Catawba Meadows Baseball Fields	Bathrooms	12/4/2020	Handicap Sink	Currently 34 3/4" high	Lower the sink to 34" high	L	L	L	Time				

						Raise the toilet paper								
	Catawba Meadows Baseball				Currently 9 1/2" above the	dispenser to 12" above the								
3.33	Fields	Bathrooms	12/4/2020	Toilet Paper Dispenser	side rail	side rail		L	L	L	Time			
	Catawba Meadows Baseball										\$5 - \$35 per			
3.43	Fields	Bathrooms	12/4/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L	L	L	stall			
	Catawba Meadows		- 1- 1			Add Van Accessible signs to								
1.11	Playground	Parking Lot	7/8/2020	Van Accessible Signs	No current signs	appropriate places	r	M	М	М	\$20 per space			
	Catawba Meadows					Extend the time of the door								
3.12	Playground	Bathrooms	11/10/2020	Door Closer	Door closes in 3 seconds	closing to at least 5 sec	ΙΙ,	м	М	М	Time			
3.12	Catawba Meadows	Datinoonis	11/10/2020	Door closer	Soap dispenser is currently	Lower the soap dispenser no	<del>                                     </del>	**			Time			The hand dryer didn't
3.28	Playground	Bathrooms	11/10/2020	Height of soap dispenser	53" high	higher than 48"	l r	М	М	М	Time			work in the bathroom
	Catawba Meadows			<u> </u>	Ĭ						\$5 - \$35 per			
3.43	Playground	Bathrooms	11/10/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L	L	L	stall			
		Front			· ·	Re-paint the handicap spots to								
1.4	City Hall	Parking Lot	5/12/2020	Handicap Parking	for handicap spots	the proper dimensions	l l	M	М	М	\$400 - \$500			
4.5	Citation	Front	E /42 /2020	Man Associate Cost	Spaces aren't the correct size		ΙΙ.				\$400 - \$500			
1.5	City Hall	Parking Lot	5/12/2020	Van Accessible Spot	for handicap spots	the proper dimensions Relocate the spots to the		M	М	М	\$400 - \$500			
		Front			Spots aren't located to the	opposite side of the parking								
1.9	City Hall	Parking Lot	5/12/2020	Handicap Parking	closest route	lot, at the trees		м	М	М	\$400 - \$500			
1.5	City Hair	Business	3/12/2020	riandicap r arming	diosest route	Lower Counter should be	H				\$ 100 \$500			
2.76	City Hall	Office	5/12/2020	Counter Size	Counter Width is 32"	widened to at least 36"		L	L	L	?			
3.20	City Hall	Bathrooms	5/12/2020	Coat Hooks in bathroom stalls	Currently 62" high	Lower to a max of 48"	1	VI	М	М	Time			
3.23	City Hall	Bathrooms	5/12/2020	Handicap Sink	Currently 36" high	Lower the sink to 34" high		L	L	L	?			
											\$5 - \$35 per			
3.43	City Hall	Bathrooms	5/12/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L	L	L	stall			
					Lines are faded and their	Repaint the lines and add an								
1.7	Collett St. Rec.	Parking Lot	6/2/2020	Handicap Parking	isn't an aisle painted	aisle at the lower entrance	ľ	M	М	М	\$400 - \$500			
	Callant Ct. Bara	Danish at 1 at	6 /2 /2020	Mary Associate Ciana	No summed sings	Add Van Accessible signs to	ΙΙ.				¢20			
1.11	Collett St. Rec.	Parking Lot Front	6/2/2020	Van Accessible Signs	No current signs	appropriate places Expand landing to 60x60		M	М	М	\$20 per space Approx.			
1.28	Collett St. Rec.	Entrance	6/2/2020	Front ramp entrance into building	Landing is to smal 60x45	minimum	ΙΙ,	м	М	М	\$2,100			
1.20	Collett St. Nec.	Littratice	0/2/2020	Tront ramp entrance into building	Landing is to sinal oox45	THIIIIII CHI	<del> </del>	VI	IVI	IVI	\$2,100			
						Replace signs with Contrasting								
						Colors, Raised Letters, and								
						Braille mounted on the latch					Approx. \$20 -			
2.38	Collett St. Rec.	Interior	6/2/2020	Signs for Rooms	Wrong Signs and Placement	side of the door			М	М	\$40 per sign			
3.20	Collett St. Rec.	Bathrooms	6/2/2020	Coat Hooks in bathroom stalls	Currently 65" high	Lower to a max of 48"			М	М	Time			
3.26	Collett St. Rec.	Bathrooms	6/2/2020	Pipes under the sink	Unprotected pipes	Insulate/protect the pipes	n	M	М	М	\$20 - \$40			
			- /- /		Soap dispenser is currently	Lower the soap dispenser no								
3.28	Collett St. Rec.	Bathrooms	6/2/2020	Height of soap dispenser	54 1/2" high	higher than 48"	r	M	М	М	Time			
3.43	Collett St. Rec.	Bathrooms	6/2/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L		1	\$5 - \$35 per stall			
5.45	Conett St. Rec.	DatinOUIIIS	0/2/2020	מווירוסאוול	Door stays open	Replace with ADA compliant	++	_	L	L	\$400 - \$1,200		+	
4.2	Collett St. Rec.	Interior	6/2/2020	Water Fountain	Currently not compliant	water fountains		м	м	М	each			
	concer ou near		3,2,2020	Trace Tourism	Salventry not compliant	When moving equipment	t ti				cucii			
		Weight				make sure to leave 36"	1 1							
E-1	Collett St. Rec.	Room	6/2/2020	Accessible Route	Currently Ok	accessible route to equip		L	L	L	Time	 		
														Cost is to restripe the
1.2	Collett St. Rec. Pool	Parking Lot	6/9/2020	Handicap Parking	Only have 2 spaces	Should have at least 4 spots	r	M	М	М	\$800 - \$1,000			parking lot
		l				Create a Van accessible				_	See			Cost would be
1.3	Collett St. Rec. Pool	Parking Lot	6/9/2020	Handicap Parking	No van accessible space	parking place	l l	M	М	М	Comments		-	incorportated in restriping
1.10	Collett St. Rec. Pool	Parking Lot	6/0/2020	Handisan Barking Cians	Signs are 26" high	Signs should be at least 60"	.	м	М	М	Time			
1.10	Collett St. Rec. POOI	Parking LOT	6/9/2020	Handicap Parking Signs	Signs are 36" high	high Add Van Accessible signs to	$\vdash\vdash$	VI	iVI	IVI	Time			
1.11	Collett St. Rec. Pool	Parking Lot	6/9/2020	Van Accessible Signs	No current signs	appropriate places	,	м	М	М	\$20 per space			
2.11	Conctt St. Net. FUUI	. arking LUL	0, 3, 2020	van Accessible Signs	140 current signs	appropriate places	<del>                                     </del>	**	141	141	Approx.			
1.20	Collett St. Rec. Pool	Curb	6/9/2020	Curb Ramp	Current ramp is too steep	Regrade curb ramp	r	м	М	М	\$1,000			No steeper than 1:12
1.23			., .,		, , , , , , , , , , , , , , , , , , ,	Add sloped entry to wading	Ħ				. ,			
Р6	Collett St. Rec. Pool	Wading Pool	6/9/2020	Entry to Pool	No sloped entry	pool	l l	M	М	М	?	 		<u>                                     </u>

						Correct rails to be between									
P67	Collett St. Rec. Pool	Pool	6/9/2020	Width between handrails entering pool	1 - 32"; 1 - 17"	20" - 24" to enter pool		М	М	М	× o				
P75	Collett St. Rec. Pool	Pool	6/9/2020	Tread depth needs to be wider	Tread depth 10" on stairs	Alter treads to be wider		М	М	М	Approx. \$4,000				
P79	Collett St. Rec. Pool	Pool	6/9/2020	Riser should be solid	Riser is currenlty open	Replace Risers		М	М	М					
3.19	Collett Ct. Dog Dogl	Dathraams	6/9/2020	All mainrage	Mirror currently at FO" bigh	Lower the mirror to 40" high		N.4			Time/\$30 -				
3.19	Collett St. Rec. Pool	Bathrooms	6/9/2020	All mirrors	Mirror currently at 50" high	or add another mirror  Add Van Accessible signs to		М	М	М	\$90				
1.11	CoMMA	Parking Lot	6/16/2020	Van Accessible Signs	No current signs	appropriate places		М	М	М	\$20 per space				
1.11	COMMINA	T di king Lot	0/10/2020	Vall Accessione signs	No current signs	арргоргасс рассэ		141	141	141	920 per space				
		Front				Extend the time of the door									
1.45	CoMMA	Entrance	6/16/2020	Door Closer	Door closes in 4 seconds	closing to at least 5 sec		М	M	М	Time				
											Approx. \$5				
2.29	CoMMA	Interior	6/16/2020	Elevator	Buttons don't have braille	Add braille to the buttons		М	М	М	per button				
					No star designating main	Add Tactile Star designating									
2.31	CoMMA	Interior	6/16/2020	Elevator	level	main level		М	M	М	\$10 - \$25				
						Replace signs with Contrasting									
						Colors, Raised Letters, and					A 620				
2.38	CoMMA	Interior	6/16/2020	Signs for Rooms	Wrong Signs and Placement	Braille mounted on the latch side of the door		М	М	М	Approx. \$20 - \$40 per sign				
2.76	CoMMA	Interior	6/16/2020	Ticket Counter	Counter is too high	Lower the counter to 36"		L	L	L	240 per 3ign				
3.20	CoMMA	Bathrooms	6/16/2020	Coat Hooks in bathroom stalls	Currently 65" high	Lower to a max of 48"	++	М	M	M	Time		-		
5.20	CONTRACT	200001113	3, 20, 2020	Code Hooks in Satinoon Stans	currency of mgm	Move down 1" to reach 54"				.*1					
3.33	CoMMA	Bathrooms	6/16/2020	Side Grab Bars in bathroom stalls	Currently 53" from wall	from the wall		L	L	L	Time				
	* *		,		,	Move flush control to the					\$120-\$500				
3.37	CoMMA	Bathrooms	6/16/2020	Flush control on the toilet	On the closed side	open side of the stall		L	L	L	per toilet				
											\$5-\$35 per				
3.43	CoMMA	Bathrooms	6/16/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L	L	L	stall				
						Replace with ADA compliant					\$400 - \$1,200				
4.2	CoMMA	Interior	6/2/2020	Water Fountain	Currently not compliant	water fountains		М	М	M	each				
						Add Van Accessible signs to									
1.11	Community House	Parking Lot	6/15/2020	Van Accessible Signs	No current signs	appropriate places		М	М	М	\$20 per space				
4.00		l	C (4 5 /2020		No signs on Inaccessible	Add signs directing people to					\$15 - \$35 per				
1.39	Community House	Entrance	6/15/2020	Handicap Entrance	doors	accessible doors		L	L	L	door				
2.38	Community House	Interior	6/15/2020	Signs for Rooms	No Braille on the Signs	Add Braille to the interior signs					Approx. \$20 per sign				
2.30	Community House	interior	0/13/2020	Signs for Rooms	NO Braille Off the Signs	Add Braille to the interior signs		_	L	-	per sign				
						Table clearance should be a					Approx. \$250				
2.66	Community House	Interior	6/15/2020	Tables	Table Clearance is 27"	minimum of 28"		L	L	L	per table				
			0, 20, 2020			Rearrange furniture to allow		_	_		per terre				
					Not enough clearance at the	for 30"x48" space at the end									
2.70	Community House	Interior	6/15/2020	Bridal Changing Area	end of the bench	of the bench		L	L	L	Time				
											\$5-\$35 per				
3.43	Community House	Bathrooms	6/15/2020	Door isn't self-closing	Door stays open	Change hinges to self closing		L	L	L	stall				
		L				Repaint the lines and add an									
1.2	Drexel Heritage Park	Parking Lot	1/4/2021	Handicap Parking Spots	No designated spots	aisle at the lower entrance	$\vdash$	М	M	М	\$400 - \$500				
1 1 1	Droval Haritaga Barl	Darking Let	1/4/2021	Handisan Barking Signs	No handican navising si	Add proper signs		M	N.4	D 4	¢20 nor can				
1.3 3.5	Drexel Heritage Park Drexel Heritage Park	Parking Lot Bathrooms	1/4/2021 1/4/2021	Handicap Parking Signs Signs for Bathrooms	No handicap parking signs  Mounted incorrectly	Add proper signs  Move the sign	$\vdash$	M	M M	M	\$20 per space Time				
3.3	Diexei neillage Park	DatiffOOIIIS	1/4/2021	Signs for bathforms	iviounted incorrectly	iviove the sign	$\vdash$	IVI	IVI	IVI	inne		1	+	
						Extend the time of the door									
3.12	Drexel Heritage Park	Bathrooms	1/4/2021	Door Closer	Door closes in 4 seconds	closing to at least 5 sec		М	М	М	Time				
3.20	Drexel Heritage Park	Bathrooms	1/4/2021	Coat Hooks in bathroom stalls	Currently 65" high	Lower to a max of 48"		М	M	M	Time				
3.26	Drexel Heritage Park	Bathrooms	1/4/2021	Pipes under the sink	Unprotected pipes	Insulate/protect the pipes		М	М	М	\$20 - \$40				
						Move down 6" to reach 54"									
3.33	Drexel Heritage Park	Bathrooms	1/4/2021	Side Grab Bars in bathroom stalls	Currently 48" from wall	from the wall		L	L	L	Time				
1						Raise the toilet paper		Ţ							
						dispenser to 12" above the									
3.33	Drexel Heritage Park	Bathrooms	1/4/2021	Toilet Paper Dispenser	Currently 10" above bar	side rail		L	L	L	Time				
3.34	Drexel Heritage Park	Bathrooms	1/4/2021	Back Grab bar location	Currently 25" long	Bar should be min. 36" long	$\vdash\vdash$	L	L	L	\$20 - \$30				
2 27	Droval Haritaga Barl	Dathraam -	1/4/2021	Eluch control on the tailet	On the classed side	Move flush control to the		, [	,	,	\$120-\$500				
3.37	Drexel Heritage Park	Bathrooms	1/4/2021	Flush control on the toilet	On the closed side	open side of the stall	$\vdash$	L	L	L	per toilet				
1.2	Forest Hill Cemetery Office	Parking Lot	5/22/2020	Handicap Parking	There is none	Add Handicap parking		М	М	М	\$400 - \$500			Restrine	parking lot
1.2	. o.coc min confectory office	, arking LUL	3/22/2020	nanacap r aixiig	mere is none	Add Hallaicap parking		141	141		7-00 - JJ00	I.		nestripe	parking lot

			1			1		1			ı	I		
1.19	Forest Hill Cemetery Office	Parking Lot	5/22/2020	Curb Ramp	There is none	Add a curb ramp		М	М	М	?			
1.37	Forest Hill Cemetery Office	Entrance	5/22/2020	Accessible Entrance	There is none	Make the entry accessible		М	М	М	?			
						Add braile to the signs and					Approx. \$20			
2.38	Forest Hill Cemetery Office	Interior	5/22/2020	Signs	There is no braille	mount correctly		L	L	L	per sign			
			44		Table/Desk doesn't have	Replace Table/Desk with					_			
2.67	Forest Hill Cemetery Office	Interior	5/22/2020	Table/Desk	enough clearance	higher clearance if needed		L	L	L	?			
2.6	5		5 /22 /222		2011	Install larger door with at least					4400 4000			
3.6	Forest Hill Cemetery Office	Bathrooms	5/22/2020	Bathroom Entrance	Door is too narrow - 30"	32" opening		М	М	М	\$100 - \$200		+	
3.16 -					Needs multiple items to be						\$1,000 -			Close the bathroom to the
3.50	Forest Hill Cemetery Office	Bathrooms	5/22/2020	Bathroom Remodel	considered ADA compliant						\$2,000			public
1.2	Freedom Park	Parking Lot		Handicap Parking	There is none	Add Handicap Parking		М	М	М	\$800 - \$1,000			Restripe parking lot
			3,2 ,,2020			Slow the door closing to 5					7-7			
3.12	Freedom Park	Bathrooms	11/10/2020	Bathroom Entrance	Door closes in 3 seconds	seconds		М	М	М	Time			
3.20	Freedom Park	Bathrooms	11/10/2020	Coat Hooks in bathroom stalls	Currently 67" high	Lower to a max of 48"		M	М	М	Time			
3.23	Freedom Park	Bathrooms	11/10/2020	Handicap Sink	Currently 37" high	Lower the sink to 34" high		L	L	L	?			
3.26	Freedom Park	Bathrooms	11/10/2020	Pipes under the sink	Unprotected pipes	Insulate/protect the pipes		М	М	М	\$20 - \$40			
					Soap dispenser is currently	Lower the soap dispenser no							1	
3.28	Freedom Park	Bathrooms	11/10/2020	Height of soap dispenser	50" high	higher than 48"	$\vdash \vdash$	М	М	М	Time			
											\$2,500 -			
2.00	Franks D. I	D-4b-	44/40/2025	Landing Co. S.	C	Move to be between 16"-18"		.			\$3,500 per		1	
3.30	Freedom Park	Bathrooms	11/10/2020	Location of toilet	Currently 19" from wall	from the wall		L	L	<u>L</u>	toilet		+	
3.31	Freedom Park	Bathrooms	11/10/2020	Width of stall	Currently the stall is 41" wide	Widen the stall to at least 60" wide		М	М	М	Approx. \$1,300		1	
3.34	Freedom Park		1/10/2020	Back Grab bar location	Currently 25" long	Bar should be min. 36" long	_	L	L	L	\$1,300			
3.34	rieedolliraik	Datilloulis	1/10/2020	Back Grab bar location	Currently 25 long	Bai siloulu be IIIII. 30 long		_			320 - 330			The door opening in, only
														provides 38" of space
														when it should provide
3.50	Freedom Park	Bathrooms	11/10/2020	Stall Door	Currently opens in	Reverse the door to open out		М	М	М	?			59"
1.2	Greenway Playground	Parking Lot	7/1/2020	Handicap Parking	Only have 1 space	Add Handicap Parking		М	М	М	\$400 - \$500			
1.3	Greenway Playground	Parking Lot	7/1/2020	Van Accessible	Currently no spaces	Add Van Accessible space		М	М	М	\$400 - \$500			
						Signs should be at least 60"								
1.10	Greenway Playground	Parking Lot	7/1/2020	Handicap Parking Signs	Sign is 28" high	high		М	М	М	Time			
					Sign isn't mounted on the	Move the sign to the latchside								
3.5	Greenway Playground	Bathrooms	10/26/2020	Sign Placement	latch side of the door	of the door		L	L	L	Time			
			/ /			Slow the door closing to 5								
3.12	Greenway Playground	Bathrooms	10/26/2020	Bathroom Entrance	Door closes in 4 seconds	seconds		M	M	M	Time			
3.20	Greenway Playground	Bathrooms Bathrooms	10/26/2020	Coat Hooks in bathroom stalls Width at sink	Currently 66" high	Lower to a max of 48"		M	М	M	Time		+	
3.21	Greenway Playground Greenway Playground	Bathrooms	10/26/2020	Pipes under the sink	Currently 29 1/2" Unprotected pipes	Should be at least 30" Insulate/protect the pipes	<del>                                     </del>	M	L M	L M	Time \$20 - \$40			
3.20	Greenway Flayground	Datilloulis	10/20/2020	ripes under the sink	Soap dispenser is currently	Lower the soap dispenser no		IVI	IVI	IVI	320 - 340			
3.28	Greenway Playground	Bathrooms	10/26/2020	Height of soap dispenser	52 1/2" high	higher than 48"		М	М	М	Time			
3.20	Greenway riaygrouna	Dutilioonis	10/20/2020	rieigne or soup dispenser	32 1/2 mgm	Move down 3 1/2" to reach			141	141	Time			
3.33	Greenway Playground	Bathrooms	10/26/2020	Side Grab Bars in bathroom stalls	Currently 50 1/2" from wall	54" from the wall		L	L	L	Time			
3.34	Greenway Playground	Bathrooms	10/26/2020	Back Grab bar location	Currently 25" long	Bar should be min. 36" long		L	L	L	\$20 - \$30			
2.1	Mainstreet Office	Entrance	7/15/2020	No Accessible Entrance	Large staircase	Add Accessible Route		Н	Н	Н	Approx.			I would recommend that
2.9	Mainstreet Office	Entrance	7/15/2020	No Elevator	Large staircase	Add Elevator		Н	Н	Н	\$30,000			we have all Mainstreet
T							1 T	T						meetings at the
						Replace signs with Contrasting							1	Community House
						Colors, Raised Letters, and								
						Braille mounted on the latch					Approx. \$20 -			
2.38	Mainstreet Office	Interior	7/15/2020	Signs for Rooms	No signs	side of the door	$\vdash \vdash$	М	М	М	\$40 per sign		+	
,	Marinatus : Off	1-4-	7/45/2020	Dane W. J.	Current door knobs aren't	Replace door knobs with ADA					Approx. \$30		1	
2.43	Mainstreet Office	Interior	7/15/2020	Door Knobs	ADA compliant	compliant knobs	$\vdash$	М	М	М	per door		+	
					Sign isn't mounted on the	Poplace with preparate					Approv 630		1	
3.5	Mainstreet Office	Bathrooms	7/15/2020	Sign Placement/Type	latch side of the door and wrong type	Replace with proper sign mounted correctly		, 1			Approx. \$20 - \$40			
3.26	Mainstreet Office	Bathrooms		Pipes under the sink	Unprotected pipes	Insulate/protect the pipes	$\vdash \vdash$	L	L	L	\$20 - \$40		+	
5.20	Manistreet Office	50111001115	111312020	ripes under the sink	Onprotected pipes	Should be mounted no higher	$\vdash \vdash$	-			720 - J <del>4</del> 0		+	
3.29	Mainstreet Office	Bathrooms	7/15/2020	Towel Dispenser	Currently 53 1/2" high	than 48"		L	L.	L	Time		1	
3.34	Mainstreet Office		7/15/2020	Back Grab bar location	Currently 25" long	Bar should be min. 36" long		L	L	L	\$20 - \$30		1	
					,	Signs should be at least 60"								
1.10	Martha's Park	Parking Lot	6/10/2020	Handicap Parking Signs	Sign is 48" high	high		М	М	М	Time	<u> </u>		<u>                                       </u>
3.20	Martha's Park		10/20/2020	Coat Hooks in bathroom stalls	Currently 67" high	Lower to a max of 48"		М	М	М	Time			

3.23	Martha's Park	Bathrooms	10/20/2020	Handicap Sink	Currently 36" high	Lower the sink to 34" high		1	1	1	?			
3.26	Martha's Park	Bathrooms		Pipes under the sink	Unprotected pipes	Insulate/protect the pipes		i		Ĺ	\$20 - \$40			
VV						Add Soap dispenser no higher				_	\$20 per			
3.28	Martha's Park	Bathrooms	10/20/2020	Soap Dispenser	Currently no soap	than 48"	N	_ N	,	М	dispenser			
											\$5-\$35 per			
3.43	Martha's Park	Bathrooms	10/20/2020	Door isn't self-closing	Door stays open	Change hinges to self closing	L	1		L	stall			
1.2	MLK Jr. Park		7/15/2020	Handicap Parking Spots	Currently only 2 spots	Need at least 4 spots	N	I N	1	M	\$400 - \$500			
	THER ST. T GIN	r ur king zot	771372020	Transacap Farming Specs	Sign isn't mounted on the	Move the sign to the latchside	- I		·		ψ.00 ψ300			
3.5	MLK Jr. Park	Bathrooms	10/27/2020	Sign Placement	latch side of the door	of the door					Time			
3.3	WIEN ST. T UTK	Butiliooilis	10/27/2020	Sign Flacement	later side of the door	Slow the door closing to 5				-	Tittle			
3.12	MLK Jr. Park	Bathrooms	10/27/2020	Bathroom Entrance	Door closes in 3 seconds	seconds	N	. I	,	м	Time			
3.20	MLK Jr. Park		10/27/2020	Coat Hooks in bathroom stalls	Currently 60" high	Lower to a max of 48"	N			M	Time			
3.20	WILK JI. F di K	Datinoonis	10/27/2020	COAL FIOOKS III DALIII OOTII SLAIIS	currently 00 mgm	Lower to a max or 48	10	<u>''</u>	<u>'                                    </u>	IVI	\$2,500 -			
						Move to be between 16"-18"					\$3,500 per			
3.30	MLK Jr. Park	Bathrooms	10/27/2020	Location of toilet	Currently 20 1/2" from wall	from the wall				,	toilet			
3.30	IVILK JI. FAIK	Batilloonis	10/2//2020	Location of tollet	Currently the stall is 42 1/2"	Widen the stall to at least 60"				_				
3.31	MLK Jr. Park	Bathrooms	10/27/2020	Width of stall	wide	wide	N	. N	.	м	Approx. \$1,300			
3.31	IVILK JI. Falk	Batilloonis	10/2//2020	Width of Stall	wide	Move down 5 1/2" to reach	IV	I IV	<u>'</u>	IVI	\$1,500			
3.33	MLK Jr. Park	Dathrooms	10/27/2020	Side Grab Bars in bathroom stalls	Currently 48 1/2" from wall	54" from the wall	l I .	Ι.		.	Time			
3.33	IVILK Jr. Park	Bathrooms	10/27/2020	Side Grab Bars III battiroom stalls	Currently 48 1/2 Irom wan						Time			
3.34	MLK Jr. Park	Dathroor	10/27/2020	Dock Crop has location	No hook wall grob !	Add back wall grab bar 36"	l I .	Ι.			¢20 ¢20			
5.34	IVILK Jr. Park	Bathrooms	10/2//2020	Back Grab bar location	No back wall grab bar	long	L	L		L	\$20 - \$30		1	
1 2 2	Mt \/io	lmtc=!	C/4/2020	Water Front-in	Currently wrong type of	Replace with ADA compliant	.			,	\$400 - \$1,200		1	
2.8	Mt. View Rec	Interior	6/4/2020	Water Fountain	water fountain	water fountain	$\Box$			L	each		+	
						[_ ,								
						Replace signs with Contrasting								
						Colors, Raised Letters, and								
2.38						Braille mounted on the latch					Approx. \$20 -			
& 3.5	Mt. View Rec	Interior	6/4/2020	Signs for Rooms	Incorrect Signs	side of the door	N	l №	1	М	\$40 per sign			
					Current door knobs aren't	Replace door knobs with ADA					Approx. \$30			
2.43	Mt. View Rec	Interior	6/4/2020	Door Knobs	ADA compliant	compliant knobs	N			M	per door			
3.19	Mt. View Rec	Bathrooms	6/4/2020	Mirrors	Currently 45" high	Move to 40" high	N			M	Time			
3.20	Mt. View Rec	Bathrooms	6/4/2020	Coat Hooks in bathroom stalls	Currently 66" high	Lower to a max of 48"	N			М	Time			
3.26	Mt. View Rec	Bathrooms	6/4/2020	Pipes under the sink	Unprotected pipes	Insulate/protect the pipes	L	L		L	\$20 - \$40			
														Recommend
														reconfiguring the
					Currently the stall is 37"	Widen the stall to at least 60"					Approx.			bathroom stalls to
3.31	Mt. View Rec	Bathrooms	6/4/2020	Width of stall	wide	wide	N			M	\$1,300			accommodate
3.33	Mt. View Rec	Bathrooms	6/4/2020	Side Grab Bars in bathroom stalls	Currently only 24" long	Side bar should be 42" long	N			M	\$35 - \$45			
3.34	Mt. View Rec	Bathrooms	6/4/2020	Back Grab Bar	Currently only 25" long	Back Bar should be 36" long	N	I №	1	M	\$20 - \$30			
						Add Van Accessible signs to								
1.11	Public Safety HQ	Parking Lot	10/13/2020	Van Accessible Signs	No current signs	appropriate places	N	I №	1	M	\$20 per space			
						Should be a minimum of 34"								
1.31	Public Safety HQ	Ramp	10/12/2020			Should be a millimum of 34								
			10/13/2020	Hand Rail	Currently 31 3/4" high	high	N	. N	1	М				
1.34			10/13/2020	Hand Rail	Currently 31 3/4" high		N	ı M	1	М				
	Public Safety HQ	Ramp	10/13/2020	Hand Rail Hand Rail	Currently 31 3/4" high  Cross Section is 3 1/4"	high	N			M M				
	Public Safety HQ	Ramp				high Should be no greater than 2					Approx.			
1.36	Public Safety HQ Public Safety HQ	Ramp Ramp				high Should be no greater than 2 1/4"		ı M	1		Approx. \$6,000			
			10/13/2020	Hand Rail	Cross Section is 3 1/4"	high Should be no greater than 2 1/4" Lower bar should be 4" or less	N	ı M	1	М				
			10/13/2020	Hand Rail	Cross Section is 3 1/4"  Lower bar is too high, 12"	high Should be no greater than 2 1/4" Lower bar should be 4" or less	N	ı M	1	М				
1.36	Public Safety HQ	Ramp	10/13/2020	Hand Rail Hand Rail	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground	N	I M	1	М	\$6,000			Only if applicable
1.36	Public Safety HQ Public Safety HQ	Ramp Interior	10/13/2020 10/13/2020 10/13/2020	Hand Rail Hand Rail Public Phone	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone	M	N	1	M M L	\$6,000 Approx. \$20			Only if applicable
1.36 4.14 4.17	Public Safety HQ Public Safety HQ Public Safety HQ	Ramp Interior Interior	10/13/2020 10/13/2020 10/13/2020 10/13/2020	Hand Rail  Hand Rail  Public Phone  Public Phone	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol	M M	I M	1	M M L	\$6,000 Approx. \$20 Approx. \$20			Only if applicable
1.36 4.14 4.17 4.18	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ	Ramp Interior Interior Interior	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Public Phone	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign	M L L	I M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20			Only if applicable
1.36 4.14 4.17 4.18 1.5	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone Public Phone Public Phone Handicap Parking Spot	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TIY Symbol  No public phone sign  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground Add pictogram to phone Add symbol Add public phone sign Reline the parking lot	M L L	M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400			Only if applicable
1.36 4.14 4.17 4.18 1.5	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone Public Phone Public Phone Handicap Parking Spot	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TIY Symbol  No public phone sign  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle	M L L	M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Handicap Parking Spot  Handicap Aisle	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a	M L L	M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 \$500			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Handicap Parking Spot  Handicap Aisle	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a	M L L	M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 \$500			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Handicap Parking Spot  Handicap Aisle	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high	M L L	M	1	M M L L	\$6,000 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 \$500			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Handicap Parking Spot  Handicap Aisle	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and	M L L	M	1	M M L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 \$500  Time			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone  Public Phone  Public Phone  Handicap Parking Spot  Handicap Aisle	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly  Current sign only 34" high	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high	M L L	M	1	M M L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$20 Time  Approx. \$20-			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7 1.10	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot Parking Lot Interior	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone Public Phone Public Phone Handicap Parking Spot Handicap Aisle  Handicap Sign	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TIY Symbol  No public phone sign  Not lined properly  Not lined properly  Current sign only 34" high	high  Should be no greater than 2 1/4"  Lower bar should be 4" or less from the ground  Add pictogram to phone  Add symbol  Add public phone sign  Reline the parking lot  Reline the aisle  Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and Braille mounted on the latch side of the door	M L L	I N	1	M M L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$400 \$500  Time  Approx. \$20 - \$40 per sign			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7 1.10	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Interior Parking Lot Parking Lot	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone Public Phone Public Phone Handicap Parking Spot Handicap Aisle  Handicap Sign	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Not lined properly  Current sign only 34" high	high  Should be no greater than 2 1/4"  Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and Braille mounted on the latch side of the door Lower to a max of 48"	M M L L L	I N	1	M L L L L L L L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$20 Time  Approx. \$20-			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7 1.10 2.38 8.3.5 3.20	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Interior Parking Lot Parking Lot Parking Lot Interior Bathrooms	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020	Hand Rail  Public Phone Public Phone Public Phone Public Phone Handicap Parking Spot Handicap Aisle Handicap Sign  Signs for Rooms Coat Hooks in bathroom stalls	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Current sign only 34" high  Incorrect Signs  Currently 66" high	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and Braille mounted on the latch side of the door Lower to a max of 48" Lower Soap dispenser to no	M M L L L	I N	1	M L L L L L L L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 Time  Approx. \$20 - \$40 per sign Time			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7 1.10	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Parking Lot Parking Lot Parking Lot Interior	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020	Hand Rail  Hand Rail  Public Phone Public Phone Public Phone Handicap Parking Spot Handicap Aisle  Handicap Sign	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TIY Symbol  No public phone sign  Not lined properly  Not lined properly  Current sign only 34" high	high  Should be no greater than 2 1/4"  Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the parking lot Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and Braille mounted on the latch side of the door Lower to a max of 48"  Lower Soap dispenser to no higher than 48"	M M L L L	I N	1	M L L L L L L L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$400 \$500  Time  Approx. \$20 - \$40 per sign			Only if applicable
1.36 4.14 4.17 4.18 1.5 1.7 1.10 2.38 8.3.5 3.20	Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Safety HQ  Public Works/Warehouse  Public Works/Warehouse  Public Works/Warehouse	Ramp  Interior Interior Interior Interior Parking Lot Parking Lot Parking Lot Interior Bathrooms	10/13/2020 10/13/2020 10/13/2020 10/13/2020 10/13/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020 5/21/2020	Hand Rail  Public Phone Public Phone Public Phone Public Phone Handicap Parking Spot Handicap Aisle Handicap Sign  Signs for Rooms Coat Hooks in bathroom stalls	Cross Section is 3 1/4"  Lower bar is too high, 12"  No pictogram for th telephone volume  No TTY Symbol  No public phone sign  Not lined properly  Current sign only 34" high  Incorrect Signs  Currently 66" high	high Should be no greater than 2 1/4" Lower bar should be 4" or less from the ground  Add pictogram to phone Add symbol Add public phone sign Reline the parking lot Reline the aisle Bottom of sign should be a minimum of 60" high  Replace signs with Contrasting Colors, Raised Letters, and Braille mounted on the latch side of the door Lower to a max of 48" Lower Soap dispenser to no	M M L L L	I N	1	M L L L L L L L L	\$6,000  Approx. \$20 Approx. \$20 Approx. \$20 Approx. \$400 Time  Approx. \$20 - \$40 per sign Time			Only if applicable

						Lengthen the stall to at least				Approx.		
3.31	Public Works/Warehouse	Bathrooms	5/21/2020	Length of stall	Currently the stall is 40" long	56" wide	L	L	L	\$1,300		
	·			<u> </u>		Side bar should be 42" long						
3.33	Public Works/Warehouse	Bathrooms	5/21/2020	Side Grab Bars in bathroom stalls	Currently only 52" long	and 54" from the back wall	L	L	L	Time		
						Add back wall grab bar 36"						
3.34	Public Works/Warehouse	Bathrooms	5/21/2020	Back Grab bar location	No back wall grab bar	long	L	L	L	\$20 - \$30		
										\$5-\$35 per		
3.43	Public Works/Warehouse	Bathrooms	5/21/2020	Door isn't self-closing	Door stays open	Change hinges to self closing	L	L	L	stall		
						Add/Replace with ADA				\$400 - \$1,200		
4.1	Public Works/Warehouse	Interior	5/21/2020	Water Fountain	Currently not compliant	Compliant water fountain	L	L	L	each		
1.10	Soccer Complex	Parking Lot	6/26/2020	Handicap Sign	, ,	Raise the sign to a min. of 60"	М	M	М	Time		
					Sign isn't mounted on the	Move the sign to the latchside						
3.5	Soccer Complex	Bathrooms	10/26/2020	Sign Placement	latch side of the door	of the door	L	L	L	Time		
						Lower handle to between 34 -						
3.10	Soccer Complex	Bathrooms	10/26/2020	Door Handles	Currently 49 1/2" high	48"	М	M	М	Time		
3.20	Soccer Complex	Bathrooms	10/26/2020	Coat Hooks in bathroom stalls	Currently 66" high	Lower to a max of 48"	L	L	L	Time		
3.26	Soccer Complex	Bathrooms	10/26/2020	Pipes under the sink	Unprotected pipes	Insulate/protect the pipes	L	L	L	\$20 - \$40		
						Add Soap dispenser no higher				\$20 per		
3.28	Soccer Complex	Bathrooms	10/26/2020	Soap Dispenser	Currently no soap	than 48"	М	M	М	dispenser		
						Side bar shouldextend 54"						
3.33	Soccer Complex	Bathrooms	10/26/2020	Side Grab Bars in bathroom stalls	Currently only 49" from wall	long	М	M	М	Time		
						Add back wall grab bar 36"						
3.34	Soccer Complex	Bathrooms	10/26/2020	Back Grab bar location	No back wall grab bar	long	М	M	M	\$20 - \$30		
										\$5-\$35 per		
3.43	Soccer Complex		10/26/2020	Door isn't self-closing	Door stays open	Change hinges to self closing	М	M	М	stall		
1.2	Soccer Complex P3	Parking Lot	1/27/2021	Handicap Parking	Currently only 3 spots	Need at least 4 spots	М	M	М	\$400 - \$500		
						Add a Van Accessible sign to						
1.11	Soccer Complex P3	Parking Lot	1/27/2021	Handicap Parking Sign	No van accessible space	the appropriate spot	L	L	L	\$20 per space		